



## 2019 Apprentice Event

### **Cutout Relocate**

Mean Time: 5 Minutes

Drop Dead Time: 10 Minutes

This event consists of relocating a cutout on a cross arm. The apprentice will use an extendo stick to open and remove the door to the cutout, then climb up to the cross arm and remove cutout from one side of the arm and reinstall on the other side. The brackets will be on the crossarm. The apprentice will climb down and remove climbers, then will reinstall the cutout door and close it. Once the door is closed the time will stop.

The Apprentice will have five minutes to set up and ask questions. The apprentice will signal when they are ready.

The apprentice shall sound the pole with a hammer prior to climbing.

Time starts when the judge signals "GO".

All tools not in use and materials shall remain on the tarp.

The time stops when the cutout door is closed.